

Notice of References Cited			Application No. 09/114,665	Applicant(s) <i>Bieler et al</i>		
			Examiner <i>S. Ig</i>	Group Art Unit 1742		
			Page <u>1</u> of <u>1</u>			
U.S. PATENT DOCUMENTS						
*	DOCUMENT NO.	DATE	NAME		CLASS	SUBCLASS
A						
B						
C						
D						
E						
F						
G						
H						
I						
J						
K						
L						
M						
FOREIGN PATENT DOCUMENTS						
*	DOCUMENT NO.	DATE	COUNTRY	NAME	CLASS	SUBCLASS
N						
O						
P						
Q						
R						
S						
T						
NON-PATENT DOCUMENTS						
*	DOCUMENT (Including Author, Title, Source, and Pertinent Pages)					DATE
U	Gibson, A.W.; Choi, S.L.; Subramanian, K. N.; Bieler, T.R., Issues regarding microstructural coarsening due to aging of eutectic tin-silver solder, Des. Reliab. Solder Solder Interconnect, Proc. Symp. (1997), 97-103.					1997
Z						
W						
X						

BEST AVAILABLE COPY

* A copy of this reference is not being furnished with this Office action.
(See Manual of Patent Examining Procedure, Section 707.05(a).)

Part of Paper No.

4